6-4-99 MD

INSPECTION LOG

ADDRESS: _____ PERMIT #: B-9860712

BLDG #5

DATE:	INSP. INITIAL	ITEMS INSPECTED	NOTES:	Corrected ?
9.21.98		EXT. SHR	1ST & 2ND FLOORS EXT. SHR OK LESS 2ND FLR MSTS @ GARAGE.	
9.25.98		EXT. SHR	3RD FLR EXT. SHR OK LESS MST GO COLLECTOR'S AROUND STAIRS	
9.28.98		EXT. SHR	HANDI FLOORS OK OK to 2ND SIDE @ F.P.	
10.30.98		FRAME	SEE NOTE FOR CORRECTIONS	
11.2.98		FRAME	OK TO INSULATE	
11.10.98		INSUL	5 units South end Insp. K&R OK. SEE NOTE FOR OTHERS.	
11.12.98		INSULATION	CORRECTIONS LISTED 11.10.98 OK; NORTH 5 UNITS OK	
		2ND SIDE	SHR SOUTH 5-UNITS OK OK TO GYP.	
11.16.98		LATH / INSULATION	INSUL @ NORTH 6-UNITS OK. LATH OK, TRUSSES OK	
		TRUSS / FRAME	FRAME OK. OK TO GYP LESS (1) 2ND LAYER @ F.P. SHAFTS.	
11.17.98		GYP NAIL	1ST LAYER SOUTH ½ UNITS LESS K #00 NOTE REMOVE	
			GYP @ F.P.'S FOR 2ND LAYER @ SHAFT APPROVAL	
11.23.98		GYP NAIL	PA/CN SEE NOTE RE FIRE WARNING ISSUED	
11.24.98		GYP NAIL	PREVIOUS CORRECTIONS LISTED ⇒ ALL GARAGES LESS 1ST LAYER OK	
			SOUTH ½ 2ND LAYER OK LESS K UNIT (1ST LAYER OK)	
			NORTH ½ 1ST LAYER OK	
11.30.98		GYP NAIL	NORTH ½ 2ND LAYER UNITS I, J & T OK 2ND LAYER @ F.P. OK	
12.2.98		GYP NAIL	2ND LAYER K UNITS (200) OK; AND GARAGES LESS NORTH ½, 3 [illegible]	
12.3.98		GYP NAIL	2ND LAYER COMPLETE ALL UNITS ALL GARAGES.	
6-1-99	D. Cerrito	FINAL	SEE NOTES ALL UNITS.	
6-3-99	D. Cerrito	Final	SEE CN	

Leah,

Should we add this document "Inspection Log" to our DOC TYPES listing?

Julie 6/7

6/8 Leah

Keep in mind separately

with notes when need

Should be final

Bld-5